

## **DVE 8031/8032** **TECHNICAL SERVICE BULLETIN #1**

**Status:** Mandatory Field Corrective Action

**Product:** DVE 8031 / 8032

**Date:** March 4, 2002


**Reference Doc:** 09.01 Deiluweit No.: 5 released on 9/5/01

**Re:** Installation of G15381- Conversion Kit DVE 803x

**Reason/Rational:** Draeger Medical has released a hardware modification to increase the vertical stability of the pendant head or pendant column.

**Solution/Procedure:** Install part number G15381- "Conversion Kit DVE 803x". Refer to Service Procedure SP00239. See "Additional Info", below.

**Devices affected:** Ceiling Supply Units DVE 8031/ 8032 up to serial number ARND-0235 (prior to May 1999), **without** combination of adjusting nut G15644 and threaded bushing / nut assembly G15643.



**Timing/When:** Next inspection or repair, but no later than August 2002.



- Additional Info:** Installation instructions can be found under SP00239, located in the Service Procedures database on Lotus Notes.
- Cost:** Costs to be captured using DrägerService Dispatch system, under job type " Architectural Rework - No Charge". An invoice will be sent to DMT upon completion of this rework, to the attention of Mr. Förster-Adler, cost center 7500. Parts to be provided free of charge, until requested completion date of August 2002.
- Ordering Info/Parts:** Order part number **G 15381- "Conversion Kit- DVE 803x"**. Please contact your customer service representative to place a no charge sales order.
- Distribution:** DrägerService (direct)

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-723-5935.